

Carrier Safety Administration

DON LACY SAFETY DIRECTOR NEW PRIME INC PRIME INC PO BOX 4208 SPRINGFIELD, MO 65083 1200 New Jersey Ave., S.E. Washington, DC 20590

March 23, 2009

In reply refer to: Your USDOT No.: 3706 Review No.: 702707/CR

Dear DON LACY.

The motor carrier safety rating for your company is:

## SATISFACTORY

This SATISFACTORY rating is the result of a review and evaluation of your safety fitness completed on March 12, 2009. A SATISFACTORY rating indicates that your company has adequate safety management controls in place to meet the safety fitness standard prescribed in 49 C.F.R. 385.5.

Please assure yourself that any specific deficiencies identified in the review report have been corrected. We appreciate your efforts toward promoting motor carrier safety throughout your company. If you have questions or require further information, please contact.

> U.S. DEPARTMENT OF TRANSPORTATION FEDERAL MOTOR CARRIER SAFETY ADMINISTRATION FEDERAL PROGRAM SPECIALIST, FMCSA 3219 EMERALD LANE, SUITE 500 JEFFERSON CITY, MO 65109-6863 Telephone No.: 573-636-3246

> > John Van Steenburg

John Van Steenburg Director, Office of Enforcement and Compliance